CHANGE LOG - ARTC DIN Lease (NSW)

Changes since 1 July 2009 -- Most recent on top

Change date	Drawing	Location	Details
23 May 2019	N456,459	Fletchers Siding, Mendoora	RLX changes
23 May 2019	N301	Telerah	CTC sign removed
4 May 2019	N407	SCT Parkes	Added new loop points
22 Mar 2019	N285,9,91,95	MFN	Remove weighbridge on 285 & other minor corrections
14 Mar 20-19	N301 >>	North Coast Line	Update of details
9 Mar 2019	N598	Milguy	Corrected siding length
21 Feb 2091	N281	Moorebank Junction	Add junction signals
4 Jan 2019	N406-13	Broken Hill Line	Drawings renumbered to 401-408 range
19 Dec 2018	N594	Narrabri Junction	Old Turrawan Rd RLX now Axle Counter
11 Dec 2018	N597	Morree	Bulus Rd RL:X now axle counter
14 Nov 2018	N455	Dubbo Yard	Added new notice re tracks 8 & 9
3 Jul 2018	N272, 273	Exeter	Some signals equipped with tilt masts
1 Jun 2018	N253	Henty/Culcairn	RLX at Baird St and Yankee Rd now equipped with Boom Gates
10 May 2018	N276	Tennesee	Signal converted to 'Controlled' 113.4 >> TE2, 113.5 >> TE1
7 May 2018	N281-282	Glenfield	Added non-commissioned points 225B & 224A for future MIT
18 Mar 2018	N558	Willow Tree	Merriwa Rd RLX now has active Ped Xing
18 Mar 2018	N552	Aberdeen	Rouchel Rd RLX now has BB
2 Feb 2018	N308,315	North Coast line	Removed reference to Coast C control desk
24 Nov 2017	N281/2	Glenfield	Drawing re-arrangement a/c commection for Moorebank IT
15 Nov 2017	N251	Albury	Signal displays amended
11 Nov 2017	N269, 270	Goulburn South	Signal displays amended
22 Sep 2017	N406	Broken Hill	Inserted missing signal BH36
22 Sep 2017	N283	Leightonfield	Position of LF8 corrected to n.p.s
22 Sep 2017	N273	Moss Vale	Position of MV74 corrected to n.p.s
29 Aug 2017	N265(239)	Cunningar	New layout commissioned
11 Aug 2017	N1293	Dombarton	Revised signal displays
11 Aug 2017	N273-279	South Line	Revised signal displays
8 Jul 2017	N292	Cooks River	Rearranged west end of run around
26 Jun 2017	N254	The Rock	Yerong St RLX now with Boom gates

2 Jun 2017Q351TamrookumSiding extended2 Jun 2017N323WiangareeRLX now Boom Gates2 Jun 2017N322KyogleSiding extended27 May 2017Q352Bromelton SCTModified end point of dual rail17 May 2017N318StockibbingalCommissioning of yard re-organisation10 Mar 2017N318GraftonFry St RLX now FL & BG31 Feb 2017N317KungalaRe-positioned sig 42-423 Jan 2017N326Bulliac & GloucesterLoop lengths16 Jan 2017N259JuneeAdded Olympic Hwy bridge (north of Junee)12 Jan 2017N359JuneeAdded Olympic Hwy bridge (north of Junee)12 Jan 2017N597Moree East SidingNew terminal connection added10 Cxt 2016N253-275Main South LineSignal review and update31 Oct 2016N436BribbareeMLI X correctly located to non-preferred side20 Oct 2016N454DubboReloated signal BH540 Cxt 2016N454DubboReloated signal BDQ20 Sep 2016N251_2,4,6South LineMinor signal locations upgraded29 Sep 2016N302PatersonGoods siding stub removed21 Aug 2016N240Stroud RoadSheet re-arrangements and introduction of Enfield Yard Drg (N248)18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Jul 2016N456Private Branch	3 Jun 2017	N572	Denman	Merriwa Rd RLX now Axle Counter
2 Jun 2017N322KyogleSiding extended27 May 2017N273ExeterRemoved Hot Box Detector17 May 2017Q352Bromelton SCTModified end point of dual rail22 Mar 2017N418StockinbingalCommissioning of yard re-organisation10 Mar 2017N318GraftonFry St RLX now FL & BG31 Feb 2017N317KungalaRe-positioned sig 42-423 Jan 2017N306Bulliac & GloucesterLoop lengths16 Jan 2017N259JuneeAdded Olympic Hwy bridge (north of Junee)12 Jan 2017Q352Bromelton SCTNew terminal connection added12 Jan 2017N597Moree East SidingNew grain siding opened27 Nov 2016N253-275Main South LineSignal review and update31 Oct 2016N417BribbareeMLI X correctly located to non-preferred side20 Oct 2016N466Broken HillRelocated signal BH514 Oct 2016N454DubboReloated signal DO28 Oct 2016N251,24,6South LineMinor signal locations upgraded29 Sep 2016N302PatersonGoods siding stub removed26 Sep 2016N304/5Stroud RoadSheet re-arrangements18 Aug 2016N267Yass JunctionNew drawing - Private Branch18 Aug 2016N267Yass JunctionNew drawing - Private Branch18 Jun 2016N454Dubo WestRLX ID56 upgraded17 Jun 2016N454Dubo WestRLX ID56 upgraded17 Jun 201	2 Jun 2017	Q351	Tamrookum	Siding extended
27 May 2017N273ExeterRemoved Hot Box Detector17 May 2017Q352Bromelton SCTModified end point of dual rail22 Mar 2017N418StockinbingalCommissioning of yard re-organisation10 Mar 2017N318GraftonFry St RLX now FL & BG13 Feb 2017N317KungalaRe-positioned sig 42-423 Jan 2017N306Bulliac & GloucesterLoop lengths16 Jan 2017N259JuneeAdded Olympic Hwy bridge (north of Junee)12 Jan 2017Q352Bromelton SCTNew terminal connection added12 Jan 2017N597Moree East SidingNew grain siding opened27 Nov 2016N253-275Main South LineSignal review and update31 Oct 2016N417BribbareeMLI X correctly located to non-preferred side20 Oct 2016N460Broken HillRelocated signal BH540 Oct 2016N454DubboReloated signal BH529 Sep 2016N302PatersonGoods siding stub removed26 Sep 2016N251,2,4,6South LineMinor signal locations upgraded29 Sep 2016N302PatersonGoods siding stub removed21 Aug 2016N242South MaurlanNew drawing - Private Branch18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Jul 2016N454Dubo WestRLX 1D56 upgraded17 Jun 2016N454Dubo WestRLX 1D56 upgraded<	2 Jun 2017	N323	Wiangaree	RLX now Boom Gates
17 May 2017 Q352 Bromelton SCT Modified end point of dual rail 22 Mar 2017 N418 Stockinbingal Commissioning of yard re-organisation 10 Mar 2017 N318 Grafton Fry St RLX now FL & BG 13 Feb 2017 N317 Kungala Re-positioned sig 42-4 23 Jan 2017 N306 Bulliac & Gloucester Loop lengths 16 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 N597 Moree East Siding New grain siding opened 27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BD5 14 Oct 2016 N454 Dubbo Relocated signal DO2 8 Oct 2016 N302 Paterson Goods siding stub removed 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N304/5 Stroud Road Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N246 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine Bast removed 29 Jun 2106 N454 Dubo West RLX D55 upgraded 17 Jun 2016 N454 Dubo West RLX 1055 upgraded 17 Jun 2016 N455 Fletcher Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N456 N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456 N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	2 Jun 2017	N322	Kyogle	Siding extended
22 Mar 2017 N418 Stockinbingal Commissioning of yard re-organisation 10 Mar 2017 N318 Grafton Fry St RLX now FL & BG 13 Feb 2017 N316 Rungala Re-positioned sig 42-4 23 Jan 2017 N306 Bulliac & Gloucester Loop lengths 16 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 N359 Wore East Siding New grain siding opened 12 Jan 2017 N397 More East Siding New grain siding opened 13 Journal N459 Main South Line Signal review and update 14 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 15 Oct 2016 N406 Broken Hill Reloated signal DO2 16 Oct 2016 N454 Dubbo Reloated signal DO2 17 Nov 2016 N351,24,6 South Line Minor signal locations upgraded 18 Oct 2016 N302 Paterson Goods siding stub removed 18 Aug 2016 N304/5 Stroud Road Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 18 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N363 Naromine Naromine East removed 19 Jun 2016 N453 Naromine Naromine East removed 29 Jun 2106 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 18 May 2016 N257 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 18 May 2016 N257 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N259 Menagle Decommissioning of Down Wayside Monitoring 10 May 2016 N459 Merrygoen Pages renumbering & commissioning of PTOS 17 May 2016 N456 N459 Merrygoen Pages renumbering & commissioning of PTOS	27 May 2017	N273	Exeter	Removed Hot Box Detector
10 Mar 2017 N318 Grafton Fry St RLX now FL & BG 13 Feb 2017 N317 Kungala Re-positioned sig 42-4 23 Jan 2017 N306 Bulliac & Gloucester Loop lengths 16 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 Q352 Bromelton SCT New terminal connection added 12 Jan 2017 N597 Moree East Siding New grain siding opened 27 Nov 2016 N25-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N302 Paterson Goods siding stub removed 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N3045 Stroud Road Sheet re-arrangement and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N3045 Stroud Road Sheet re-arrangement 18 Aug 2016 N251 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N454 Dubo West RLX 1056 uggraded 31 May 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451 N452 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	17 May 2017	Q352	Bromelton SCT	Modified end point of dual rail
13 Feb 2017 N317 Kungala Re-positioned sig 42-4 23 Jan 2017 N306 Bulliac & Gloucester Loop lengths 16 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 Q352 Bromelton SCT New terminal connection added 12 Jan 2017 N597 Moree East Siding New grain siding opened 27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 41 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N302 Paterson Goods siding stub removed 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N304/S Stroud Road Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/S Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N453 Naromine Naromine East removed 29 Jun 2106 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N259 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	22 Mar 2017	N418	Stockinbingal	Commissioning of yard re-organisation
23 Jan 2017N306Bulliac & GloucesterLoop lengths16 Jan 2017N259JuneeAdded Olympic Hwy bridge (north of Junee)12 Jan 2017Q352Bromelton SCTNew terminal connection added12 Jan 2017N597Moree East SidingNew grain siding opened27 Nov 2016N253-275Main South LineSignal review and update31 Oct 2016N407BribbareeMLI X correctly located to non-preferred side20 Oct 2016N406Broken HillRelocated signal BH540 Ct 2016N454DubboReloated signal DO28 Oct 2016N251,2,4,6South LineMinor signal locations upgraded29 Sep 2016N302PatersonGoods siding stub removed26 Sep 2016N286-N288EnfieldSheet re-arrangements and introduction of Enfield Yard Drg (N248)21 Aug 2016N304/5Stroud RoadSheet re-arrangement18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Aug 2016N216FramptonLocation dismantled15 Jul 2016N453NaromineNaromine East removed29 Jun 2106N454Dubo WestRLX 1056 upgraded17 Jun 2016N456Fletchers SidingMeasurements added31 May 2016N252Table opRLX 228 Equipped with prefictor & Boom gates10 May 2016N451-N454Goobang Jcn-Minore BPPages renumbering & commissioning of PTOS7 May 2016N456-N459Merrygoen-Troy JunctionPages renumbering & commissioning of PTOS <td>10 Mar 2017</td> <td>N318</td> <td>Grafton</td> <td>Fry St RLX now FL & BG</td>	10 Mar 2017	N318	Grafton	Fry St RLX now FL & BG
16 Jan 2017 N259 Junee Added Olympic Hwy bridge (north of Junee) 12 Jan 2017 Q352 Bromelton SCT New terminal connection added 12 Jan 2017 N597 Moree East Siding New grain siding opened 27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 11 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N451 N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 1 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 1 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	13 Feb 2017	N317	Kungala	Re-positioned sig 42-4
12 Jan 2017 Q352 Bromelton SCT New terminal connection added 12 Jan 2017 N597 Moree East Siding New grain siding opened 27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal BD2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Icn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	23 Jan 2017	N306	Bulliac & Gloucester	Loop lengths
12 Jan 2017 NS97 Moree East Siding New grain siding opened 27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BHS 14 Oct 2016 N454 Dubbo Relocated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N246 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	16 Jan 2017	N259	Junee	Added Olympic Hwy bridge (north of Junee)
27 Nov 2016 N253-275 Main South Line Signal review and update 31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N303 Paterson Goods siding stub removed 26 Sep 2016 N304/5 Stroud Road Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 17 Jun 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	12 Jan 2017	Q352	Bromelton SCT	New terminal connection added
31 Oct 2016 N417 Bribbaree MLI X correctly located to non-preferred side 20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N458-N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	12 Jan 2017	N597	Moree East Siding	New grain siding opened
20 Oct 2016 N406 Broken Hill Relocated signal BH5 14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N304/5 Stroud Road Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	27 Nov 2016	N253-275	Main South Line	Signal review and update
14 Oct 2016 N454 Dubbo Reloated signal DO2 8 Oct 2016 N251,2,4,6 South Line Minor signal locations upgraded 29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	31 Oct 2016	N417	Bribbaree	MLI X correctly located to non-preferred side
8 Oct 2016N251,2,4,6South LineMinor signal locations upgraded29 Sep 2016N302PatersonGoods siding stub removed26 Sep 2016N286-N288EnfieldSheet re-arrangements and introduction of Enfield Yard Drg (N248)21 Aug 2016N304/5Stroud RoadSheet re-arrangement18 Aug 2016N242South MaurlanNew drawing - Private Branch18 Aug 2016N216FramptonLocation dismantled15 Jul 2016N453NaromineNaromine East removed29 Jun 2106N267Yass JunctionMinor location changes17 Jun 2016N454Dubo WestRLX ID56 upgraded17 Jun 2016N456Fletchers SidingMeasurements added31 May 2016N252Table opRLX 228 Equipped with prefictor & Boom gates10 May 2016N279MenagleDecommissioning of Down Wayside Monitoring9 May 2016N451-N454Goobang Jcn-Minore BPPages renumbering & commissioning of PTOS7 May 2016N581-N582Gulgong - MerrygoenPages renumbering & commissioning of PTOS7 May 2016N456-N459Merrygoen-Troy JunctionPages renumbering & commissioning of PTOS	20 Oct 2016	N406	Broken Hill	Relocated signal BH5
29 Sep 2016 N302 Paterson Goods siding stub removed 26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	14 Oct 2016	N454	Dubbo	Reloated signal DO2
26 Sep 2016 N286-N288 Enfield Sheet re-arrangements and introduction of Enfield Yard Drg (N248) 21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	8 Oct 2016	N251,2,4,6	South Line	Minor signal locations upgraded
21 Aug 2016 N304/5 Stroud Road Sheet re-arrangement 18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	29 Sep 2016	N302	Paterson	Goods siding stub removed
18 Aug 2016 N242 South Maurlan New drawing - Private Branch 18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	26 Sep 2016	N286-N288	Enfield	Sheet re-arrangements and introduction of Enfield Yard Drg (N248)
18 Aug 2016 N216 Frampton Location dismantled 15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	21 Aug 2016	N304/5	Stroud Road	Sheet re-arrangement
15 Jul 2016 N453 Naromine Naromine East removed 29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	18 Aug 2016	N242	South Maurlan	New drawing - Private Branch
29 Jun 2106 N267 Yass Junction Minor location changes 17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	18 Aug 2016	N216	Frampton	Location dismantled
17 Jun 2016 N454 Dubo West RLX ID56 upgraded 17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	15 Jul 2016	N453	Naromine	Naromine East removed
17 Jun 2016 N456 Fletchers Siding Measurements added 31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	29 Jun 2106	N267	Yass Junction	Minor location changes
31 May 2016 N252 Table op RLX 228 Equipped with prefictor & Boom gates 10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	17 Jun 2016	N454	Dubo West	RLX ID56 upgraded
10 May 2016 N279 Menagle Decommissioning of Down Wayside Monitoring 9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	17 Jun 2016	N456	Fletchers Siding	Measurements added
9 May 2016 N451-N454 Goobang Jcn-Minore BP Pages renumbering & commissioning of PTOS 7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	31 May 2016	N252	Table op	RLX 228 Equipped with prefictor & Boom gates
7 May 2016 N581-N582 Gulgong - Merrygoen Pages renumbering & commissioning of PTOS 7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	10 May 2016	N279	Menagle	Decommissioning of Down Wayside Monitoring
7 May 2016 N456-N459 Merrygoen-Troy Junction Pages renumbering & commissioning of PTOS	9 May 2016	N451-N454	Goobang Jcn-Minore BP	Pages renumbering & commissioning of PTOS
	7 May 2016	N581-N582	Gulgong - Merrygoen	Pages renumbering & commissioning of PTOS
4 May 2016 N293 Botany yard Added Banksmeadow Waste Transfer terminal	7 May 2016	N456-N459	Merrygoen-Troy Junction	Pages renumbering & commissioning of PTOS
	4 May 2016	N293	Botany yard	Added Banksmeadow Waste Transfer terminal

14 Apr 2016 N457-N464 Merrygoen-Gap Pages renumbering & commissioning of PTOS 4 Apr 2016 N456 Troy Junction New active RLX60 @ 468.721 4 Mar 2016 N1292 Summit Tank Frame B and engineers siding removed 4 Mar 2016 N273 Moss Vale NSW Trains Siding area defined 7 Feb 2016 N33 Minore Added signals 3 Jan 2016 N265 Demondrille Cowra line disconnected & Up main straight-railed 6 Nov 2015 N460 Bakana RLX now axle counter controlled 6 Sep 2015 N418 Stockibingal Surplus track removed 11 Aug 2015 N266 Goondah Goondah R RLX is ID358 5 Aug 2015 N322 Nammoona Amended signal number displays 19 Jun 2015 N455 Dubbo Triangle additions - pts 112,114 Signals 43, 48 17 Jun 2015 N256 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 11 Aug 2015 N455 Dubbo Removed Frame G and associated siding 14 Mar 2015 N310 Rossglen Added ID of RLX 4 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Siding sermoved 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 15 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N298 Campsie Corrected TO number 26 Aug 2014 N298 Campsie Corrected Gooms signal language 28 Aug 2014 N298 Campsie Corrected To number of and associated points 30 Aug 2014 N298 Port Botany Corrected To number Goods Siding sermoved 10 Corrected TO number 20 Jun 2014 N298 Campsie Corrected To number of and boom gates 15 Oct 2014 N298 Campsie Corrected Signal G12.8 3 Aug 2014 N298 Port Botany Corrected Signal G12.8 3 Aug 2014 N298 Campsie Corrected Signal G12.8 3 Aug 2014 N298 Port Botany Corrected Signal G12.8 3 Aug 2014 N299 Port Botany Corrected Signal G12.8 3 Aug 2014 N299 Port Botany Corrected Signal G12.8 3 Aug 2014 N299 Port Botany Added SICTL bew siding #4	14 Apr 2016	N597	Morree - Moree South	Commissioning of PTOS
24 Mar 2016N1292Summit TankFrame B and engineers siding removed4 Mar 2016N273Moss ValeNSW Trains Siding area defined7 Feb 2016N453MinoreAdded signals3 Jan 2016N265DemondrilleCowra line disconnected & Up main straight-railed6 Nov 2015N460BakanaRLX now axie counter controlled65 Sep 2015N418StockinbingalSurplus track removed11 Aug 2015N266GoondahGoondah Rd RLX is ID3585 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N325DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N279MenangleWayside Monitorinr installed on Down Main17 Jun 2015Q351TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignalling re-arrangement (of MU's)14 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015N351TamrookumAdded ID of RLX44 Mar 2015N304DungogRevised some signal head depictions & added Dungog Nth Loop length2 Feb 2015N409KinalungCorrected TO number27 Jan 2015N411CondobolinGrain siding now Grain Corp41 Nov 2014N294Port BotanyInter terminal road LX removed15 Oct 2014N319KoolkhanRLX 472 now upgraded and boom gates15 Oct 2014N295Cunn	14 Apr 2016	N457-N464	Merrygoen-Gap	
4 Mar 2016N273Moss ValeNSW Trains Siding area defined7 Feb 2016N453MinoreAdded signals3 Jan 2016N265DemondrilleCowra line disconnected & Up main straight-railed6 Nov 2015N460BakanaRLX now axle counter controlled26 Sep 2015N418StockinbingalSurplus track removed11 Aug 2015N266GoondahGoondah Rd RLX is iD3585 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N455DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N279MenangleWayside Monitorinr installed on Down Main17 Jun 2015Q351TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignalling re-arrangement (of MLI's)44 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015N310RossglenAdded ID of RLX4 Feb 2015N304DungogRevised some signal head depictions & added Dungog Nth Loop length2 Feb 2015N409KinalungCorrected TO number27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N449Port BotanyInter terminal road LX removed14 Nov 2014N294Port BotanyInter terminal road LX removed15 Oct 2014N319KoolkhanRLX 472 now upgraded and boom gates15 Oct 2014N265CunningarPoint	4 Apr 2016	N456	Troy Junction	New active RLX60 @ 468.721
7 Feb 2016N453MinoreAdded signals3 Jan 2016N265DemondrilleCowra line disconnected & Up main straight-railed6 Nov 2015N460BakanaRLX now axle counter controlled6 Sep 2015N418StockinbingalSurplus track removed11 Aug 2015N266GoondahGoondah Rd RLX is ID3585 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N455DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N279MenangleWayside Monitorinr installed on Down Main17 Jun 2015Q351TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignalling re-arrangement (of MLI's)14 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015N310RossglenAdded ID of RLX24 Mar 2015N310RossglenAdded ID of RLX24 Feb 2015N409KinalungCorrected TO number2 Feb 2015N408DarnickCorrected TO number2 Feb 2015N408DarnickCorrected TO number27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N454DubboGoods Sidings removed21 Oct 2014N394Port BotanyInter terminal road LX removed21 Oct 2014N395RoolkhanRLX 472 now upgraded and boom gates15 Oct 2014N265Cunningar	24 Mar 2016	N1292	Summit Tank	Frame B and engineers siding removed
3 Jan 2016N265DemondrilleCowra line disconnected & Up main straight-railed6 Nov 2015N460BakanaRLX now axie counter controlled26 Sep 2015N418StockinbingalSurplus track removed11 Aug 2015N266GoondahGoondah RLX is ID3585 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N455DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N459MenangleWayside Monitorinr installed on Down Main17 Jun 2015Q351TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignaling re-arrangement (of MLI's)14 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015Q351TamrookumAdded ID of RLX24 Mar 2015N310RossglenAdded ID of RLX24 Mar 2015N340DungogRevised some signal head depictions & added Dungog Nth Loop length2 Feb 2015N408DarnickCorrected TO number27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N454DubboGoods Sidings removed21 Jan 2015N451CondobolinGrain siding now Grain Corp14 Nov 2014N294Port BotanyInter terminal road LX removed15 Oct 2014N296Port BotanyInter terminal road LX removed <td>4 Mar 2016</td> <td>N273</td> <td>Moss Vale</td> <td>NSW Trains Siding area defined</td>	4 Mar 2016	N273	Moss Vale	NSW Trains Siding area defined
6 Nov 2015 N460 Bakana RLX now axle counter controlled 26 Sep 2015 N418 Stockinbingal Surplus track removed 11 Aug 2015 N266 Goondah Goondah Rd RLX is ID358 5 Aug 2015 N322 Nammoona Amended signal number displays 19 Jun 2015 N455 Dubbo Triangle additions - pts 112,114 Signals 43, 48 17 Jun 2015 N279 Menangle Wayside Monitorinr installed on Down Main 17 Jun 2015 Q351 Tamrookum Private road re-positioned 17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLl's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 4 Feb 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N444 Dubbo Goods Sidings removed 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 10 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N299 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N289 Junee Removed Frame C and all associated points	7 Feb 2016	N453	Minore	Added signals
26 Sep 2015N418StockinbingalSurplus track removed11 Aug 2015N266GoondahGoondah R RLX is ID3585 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N455DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N279MenangleWayside Monitorinr installed on Down Main17 Jun 2015N285TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignalling re-arrangement (of MLI's)14 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015N351TamrookumAdded ID of RLX24 Mar 2015N304DungogRevised some signal head depictions & added Dungog Nth Loop length2 Feb 2015N409KinalungCorrected TO number2 Feb 2015N409KinalungCorrected TO number2 Feb 2015N408DarnickCorrected TO number27 Jan 2015N411CondobolinGrain siding now Grain Corp14 Nov 2014N294Port BotanyInter terminal road LX removed21 Oct 2014N319KoolkhanRLX 472 now upgraded and boom gates15 Oct 2014N326CunningarPoints renumbered to actual (103A/B)13 Sep 2014N298CampsieCorrected Signal G12.83 Aug 2014N298CampsieCorrected Signal G12.83 Aug 2014N299Port BotanyCorrected Signal G12.8 <td>3 Jan 2016</td> <td>N265</td> <td>Demondrille</td> <td>Cowra line disconnected & Up main straight-railed</td>	3 Jan 2016	N265	Demondrille	Cowra line disconnected & Up main straight-railed
11 Aug 2015 N266 Goondah Goondah Goondah Rd RLX is ID358 5 Aug 2015 N322 Nammoona Amended signal number displays 19 Jun 2015 N455 Dubbo Triangle additions - pts 112,114 Signals 43, 48 17 Jun 2015 N279 Menangle Wayside Monitorinr installed on Down Main 17 Jun 2015 Q351 Tamrookum Private road re-positioned 17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 14 Apr 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 2 Jan 2015 N454 Dubbo Goods Sidings removed 2 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected Signal G12.8 3 Aug 2014 N299 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	6 Nov 2015	N460	Bakana	RLX now axle counter controlled
5 Aug 2015N322NammoonaAmended signal number displays19 Jun 2015N455DubboTriangle additions - pts 112,114 Signals 43, 4817 Jun 2015N279MenangleWayside Monitorinr installed on Down Main17 Jun 2015Q351TamrookumPrivate road re-positioned17 Jun 2015N285EnfieldWestSignal corrections30 May 2015N410MatakanaSignalling re-arrangement (of MLI's)14 Apr 2015N455DubboRemoved Frame G and associated siding24 Mar 2015N310RossglenAdded ID of RIX24 Mar 2015N310RossglenAdded ID of RIX4 Feb 2015N304DungogRevised some signal head depictions & added Dungog Nth Loop length2 Feb 2015N409KinalungCorrected TO number2 Feb 2015N408DarnickCorrected TO number27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N454DubboGoods Sidings removed27 Jan 2015N411CondobolinGrain siding now Grain Corp14 Nov 2014N294Port BotanyInter terminal road LX removed21 Oct 2014N319KoolkhanRIX 472 now upgraded and boom gates15 Oct 2014N265CunningarPoints renumbered to actual (103A/B)13 Sep 2014N277PictonAdded missing signal MN2728 Aug 2014N294Port BotanyCorrected geographical layout4 Jul 2014N289CampsieCorrected geographical layout <td>26 Sep 2015</td> <td>N418</td> <td>Stockinbingal</td> <td>Surplus track removed</td>	26 Sep 2015	N418	Stockinbingal	Surplus track removed
19 Jun 2015 N455 Dubbo Triangle additions - pts 112,114 Signals 43, 48 17 Jun 2015 N279 Menangle Wayside Monitorinr installed on Down Main 17 Jun 2015 Q351 Tamrookum Private road re-positioned 17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 24 Mar 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RIX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissiong of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	11 Aug 2015	N266	Goondah	Goondah Rd RLX is ID358
17 Jun 2015 N279 Menangle Wayside Monitorinr installed on Down Main 17 Jun 2015 Q351 Tamrookum Private road re-positioned 17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLl's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 N351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 24 Mar 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 2 Feb 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 15 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	5 Aug 2015	N322	Nammoona	Amended signal number displays
17 Jun 2015 Q351 Tamrookum Private road re-positioned 17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N451 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 3 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	19 Jun 2015	N455	Dubbo	Triangle additions - pts 112,114 Signals 43, 48
17 Jun 2015 N285 EnfieldWest Signal corrections 30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 3 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissiong of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	17 Jun 2015	N279	Menangle	Wayside Monitorinr installed on Down Main
30 May 2015 N410 Matakana Signalling re-arrangement (of MLI's) 14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 15 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	17 Jun 2015	Q351	Tamrookum	Private road re-positioned
14 Apr 2015 N455 Dubbo Removed Frame G and associated siding 24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N299 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	17 Jun 2015	N285	EnfieldWest	Signal corrections
24 Mar 2015 Q351 Tamrookum Added ID of RLX 24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N299 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	30 May 2015	N410	Matakana	Signalling re-arrangement (of MLI's)
24 Mar 2015 N310 Rossglen Added ID of RLX 4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	14 Apr 2015	N455	Dubbo	Removed Frame G and associated siding
4 Feb 2015 N304 Dungog Revised some signal head depictions & added Dungog Nth Loop length 2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	24 Mar 2015	Q351	Tamrookum	Added ID of RLX
2 Feb 2015 N409 Kinalung Corrected TO number 2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	24 Mar 2015	N310	Rossglen	Added ID of RLX
2 Feb 2015 N408 Darnick Corrected TO number 27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	4 Feb 2015	N304	Dungog	Revised some signal head depictions & added Dungog Nth Loop length
27 Jan 2015 N454 Dubbo Goods Sidings removed 27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	2 Feb 2015	N409	Kinalung	Corrected TO number
27 Jan 2015 N411 Condobolin Grain siding now Grain Corp 14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	2 Feb 2015	N408	Darnick	Corrected TO number
14 Nov 2014 N294 Port Botany Inter terminal road LX removed 21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	27 Jan 2015	N454	Dubbo	Goods Sidings removed
21 Oct 2014 N319 Koolkhan RLX 472 now upgraded and boom gates 15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	27 Jan 2015	N411	Condobolin	Grain siding now Grain Corp
15 Oct 2014 N265 Cunningar Points renumbered to actual (103A/B) 13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	14 Nov 2014	N294	Port Botany	Inter terminal road LX removed
13 Sep 2014 N277 Picton Added missing signal MN27 28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	21 Oct 2014	N319	Koolkhan	RLX 472 now upgraded and boom gates
28 Aug 2014 N298 Campsie Corrected signal G12.8 3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	15 Oct 2014	N265	Cunningar	Points renumbered to actual (103A/B)
3 Aug 2014 N294 Port Botany Corrected geographical layout 4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	13 Sep 2014	N277	Picton	Added missing signal MN27
4 Jul 2014 N289-291 Marrickville - Enfield Commissioing of signal upgrade 2 Jul 2014 N259 Junee Removed Frame C and all associated points	28 Aug 2014	N298	Campsie	Corrected signal G12.8
2 Jul 2014 N259 Junee Removed Frame C and all associated points	3 Aug 2014	N294	Port Botany	Corrected geographical layout
	4 Jul 2014	N289-291	Marrickville - Enfield	Commissioing of signal upgrade
29 Jun 2014 N294 Port Botany Added SICTL bew siding #4	2 Jul 2014	N259	Junee	Removed Frame C and all associated points
	29 Jun 2014	N294	Port Botany	Added SICTL bew siding #4

21 Jun 2014	N310	Rossglen	New active RLX @ 428.407
10 Jun 2014	N7xx series	Sydney MFN	Renumbered into N2xx series (280 - 299)
3 Jun 2014	N418	Stockinbingal-Coota West	Section converted from Token working to rail vehicle detection
29 May 2014	N453	Narromine	RLX ID59 fitted with boom gates
26 Feb 2014	N275	Mittagong	Removal of surplus points
17 Dec 2013	N707&717	Sydney MFN	Amended limitation of ARTC
26 Nov 2013	N271	Marulan	Removed "C" Xover
29 Sep 2013	N700 series	MFN	702-3-4-5-6-15-17 Refernces to RailCorp changed to Sydney Trains
30 Aug 2013	N455	Dubbo	J frame out of service
7 Aug 2013	N306	Gloucester	New active RLX 446 - Philip Street
28 Jul 2013	N273	Henty	Re-instated Henty West
12 Jul 2013	N720	Port Botany	Penrhyn Rd RLX removed
12 Jul 2013	N314	Macksville	Tilly Willy Rd now has protected Ped Crossing
11 Jul 2013	N306	Gloucester	Philp St RLX moved
10 Jul 2013	N305	Wards River	Altered the distance of RLX ID601
6 Jun 2013	N314	Macksville	Signalling rationalisation
31 May 2013	N311 & 313-6	North Coast Line	Added missing Intermediate section signals
29 May 2013	N268	Breadalbane	Added missing signals
29 May 2013	N407	Broken Hill	Corrected t/o 104 configuration
24 May 2013	N308	Wingham	Signal and RLX re-arrangements
24 May 2013	N307	Killawarra	Moved RLX 603 to this sheet
22 May 2013	N261	Section	Added Missing Signals
13 May 2013	N264	Nubba	Corrected signal 258.8
30 Apr 2013	N538	Kooragang	Revised points 107 - 108
18 Apr 2013	N318	Grafton	Corrected sig No. 45-3
18 Apr 2013	N304	Dungog	Corrected sig No. 07-22
6 Apr 2013	N271	Lynwood Junction	Commissioning new siding
22 Feb 2013	N268/9	Joppa Jcn + Goulburn	Signal corrections
14 Feb 2013	N416	Wirrinya	New shunt notice
25 Jan 2013	N308	Taree	New RLX462
20 Dec 2012	N277	Tahmoor	Redbank tunnel by-passed
18 Dec 2012	N314	Nambucca Heads	New RLX @ 569.034
17 Dec 2012	N320	Camira Creek	New RLX @ 757.168

17 Dec 2012	N701-06	SSFL	Commissioning of SSFL
17 Dec 2012	N279	Glenlee	Commissioning of SSFL
7 Dec 2012	N411	Ootha	Oootha now only a Block Point
11 Nov 2012	N254	The Rock	Changes for TOW of Boree Creek Branch Line
4 Oct 2012	N415	Parkes South	GJ123 altered
4 Oct 2012	N413	Goobang Junction	Lay of points 221
22 Sep 2012	N418	Stockinbingal	Changes fpr TO working on Griffith line
18 Sep 2012	N458	Binnaway	2H points equipped with directional Points indicator
8 Sep 2012	N315	Sawtell	Hulberts Rd RLX upgraded
29 Jul 2012	N269	Joppa Junction	Changes for implementation of Train Order working on Canberra line
6 Jul 2012	N273	Moss Vale	MV 59, MV73 and CPs were missing
6 Jul 2012	N274	Moss Vale	CP 125 was missing
25 Jun 2012	N315	Coffs harbour	New active RLX ID479
31 May 2012	N411	Condobolin	Frame & Xover 'D' removed
24 May 2012	N271	Lynwood Junction	New turnouts for Quarry Sdiding
18 May 2012	N453	Narromine	Changes for implementation of Train Order working on Cobar line
23 Jan 2012	N559	Bells Gate	Commissioning of Bells Gate Loop
23 Jan 2012	N560	Quipolly	Commissioning of Bells Gate Loop
11 Jan 2012	various	network	Changes throughout to reflect lease change of CRN from ARTC to JHR (eff 16/1/12)
9 Jan 2012	N269	Joppa Junction	Signal G7 now PW/R
8 Dec 2011	N279	Glenlee	Bidirection working commissioned to Menangle
7 Dec 2011	N598	Camurra	RLX 522 now Axel Counter
28 Nov 2011	N413	Goobang Jcn	N-R lay of points 221 reversed and signal GJ127 relocated and boundary noe 446.950
26 Nov 2011	N453	Narromine	Signal changes to Y & W
22 Oct 2011	N577	Wilpinjong	Commissioned new loop
18 Sep 2011	N278	Maldon	Commissioning of B-Directional working
18 Sep 2011	N277	Picton	Commissioning of B-Directional working
8 Sep 2011	N410	Matakana	Added new TO on loop for siding
31 Aug 2011	N305	Craven North	Stratford Colliery Loop changed
25 Aug 2011	N315	Bonville	Bonville Ck km corrected
1 Aug 2011	N720	Port Botany	Re-arrangement of crossover 176
29 Jul 2011	N262	Cootamundra	Added Dirnaseer Rd Bridge
29 Jul 2011	N261	Cootamundra	Added SL at Cowcumbla Rd

16 Jul 2011	N279	Glenlee-Menangle Park	New crossovers 93, 94, 95
1 Jul 2011	N595-598	Narrabri-North Star	Transferred to ARTC Lease from CRN - new Drawings
1 Jul 2011	N585-594	Gap-Narrabri Jcn	Transferred to ARTC Lease from CRN - new Drawings
20 Jun 2011	N704/5	SSFL	Enfield West to Leightonfield commissioned
21 May 2011	N406	Broken Hill	TO 319 to Perilya commissioned
13 May 2011	N406	Broken Hill	TO 319 to Perilya installed
13 May 2011	N278	Picton	Down Refuge & Siding removed
20 Apr 2011	N271	Marulan	Signal 197.5 moved for new road bridge
22 Mar 2011	N254	Yerong Creek	Several signals were wrongly labelled
21 Mar 2011	N253	Henty	Signal 9-4 no longer exists
28 Feb 2011	Q352	Bromelton	T/O 53 & derail rearranged. Loop length corrected
15 Feb 2011	N309	Kundle Kundle	Devlopment of RLX ID466
18 Dec 2010	N308	Taree	Overpass should be Wingham Road
18 Dec 2010	N310	Herons Creek	RLX has boom gates
18 Dec 2010	N320	Raeleigh	Siganls use new designation
11 Dec 2010	N318	Grafton	Grafton City G5 TO o.o.s and Grafton Yard track E-> G frame added
10 Dec 2010	N454	Troy Junction	Sig TJ20/21 renumbered
10 Dec 2010	N451	Alectown West	E frame o.o.s
10 Dec 2010	N305	North Craven	TO56 renumbered
10 Dec 2010	N279	Glenlee	Major Signal alterations
10 Dec 2010	N259	Junee	Frames 1C & 4C o.o.s
10 Dec 2010	N255	Uranquinty	Frames B & C o.o.s
10 Dec 2010	N253	Henty	C Vframe unusable. Added Sig 09-30
10 Dec 2010	N252	Table Top	Loop o.o.s
10 Dec 2010	N251	Albury	Frame H o.o.s
26 Nov 2010	N413	Goobang Jcn	Corrected number of Up main Home
26 Nov 2010	N279	Macarthur	New signalling for SSFL
17 Nov 2010	Q353	Acacia Ridge	Additional signal details
2 Nov 2010	N459	Connemarra	Loop now dead end
2 Nov 2010	N454	Dubbo	Track removed
27 Oct 2010	N416	Quandialla	New loop commissioned
27 Oct 2010	N314,315,319	General	Minor errors corrected
27 Oct 2010	N307-8	Various	Minor errors corrected

26 Oct 2010	N313	Kempsey	Added missing signal 30-14 & corrected other station codes
16 Oct 2010	N535	Bullock Island	Added Xover to Brambles Loop
16 Oct 2010	N251	Albury	Added Signal AY163
1 Oct 2010	N410-11	Kiacatoo	New Loop
28 Sep 2010	N413	Goobang Junction	Signal designations 133 & 131 corrected
8 Sep 2010	N304	Dungog	Missing Signals added
8 Sep 2010	N305	Duralie	Missing Signals added
8 Sep 2010	N512	Drayton Junction	Missing Signals added
3 Sep 2010	N415	Stockinbinbal - Parkes line	Chages to implement Train Order Working
3 Sep 2010	N416	Stockinbinbal - Parkes line	Chages to implement Train Order Working
3 Sep 2010	N417	Stockinbinbal - Parkes line	Chages to implement Train Order Working
3 Sep 2010	N418	Stockinbinbal - Parkes line	Chages to implement Train Order Working
2 Sep 2010	N459	Spring Ridge	Tungenbone Rd RLX is Axle Counter
20 Aug 2010	N273	Exeter	Removed X overs
16 Aug 2010	N267	Yass Junction	Amended Signals
16 Aug 2010	N720	Port Botany	New Active RLX
13 Aug 2010	N409	Ivanhoe	new Loop
21 Jul 2010	N251	Albury	Sig changes
14 Jul 2010	All drawings	with an active RLX.	Major review of all active RLX and ID numbers. Changes as required.
			Listed below - 1 drawing with RLX added
14 Jul 2010	N301	Oakhampton	Added missing RLX at Oakhampton Rd
11 Jul 2010	N305	Wards River	Terreel Rd LX = ID 601, Woods RD LX = ID602
11 Jul 2010	N308	Wingham	Dollys Flat Rd LX = ID603
11 Jul 2010	N313	Kempey	Collombatti Link Rd LX = ID604
11 Jul 2010	N314	Eungai	South Bank Rd LX = ID605, Browns Crossing LX = ID606
11 Jul 2010	N316	Nana Glen	Eastbank Rd LX = ID607
11 Jul 2010	N320	Leville	Shannonrook Rd LX = ID475
7 Jul 2010	N409	Trida	New Active LX
1 Jul 2010	N268	Cullerin	New active LX at 256.489
25 Jun 2010	N409	Darnick	Active LX at Pooncarie Rd & changed mli's
21 Jun 2010	N410-11	Condobolin AWB	Now on 411
18 Jun 2010	N412	Gunningbland	New Active RLX @ 496.285
	11412	Guillingbialla	New Active NEX @ 430.203
18 Jun 2010	N456	Dobbo	New Active RLX @ 465.754

16 Jun 2010	N252	Ettamogah	Corrected track layout @ ERH
16 Jun 2010	N252	Gerpgery	Corrected several signal numbers
16 Jun 2010	N253	Culcairn	Passing Loop 14 commissioned
16 Jun 2010	N502	Waratah	Added Up siding
16 Jun 2010	N511	Newdell Junction	Added Sigs NJ 24, 165.1, 166.3, 165.2 & 166.6
16 Jun 2010	N512	Drayton Junction	Added Sig DJ76
16 Jun 2010	N510	Singleton	RE-converted Xover 2B to manual
16 Jun 2010	Q352	Bromleton	Introduced dual gauge track
16 Jun 2010	Q452	Greenbank	Introduced dual gauge track
15 Jun 2010	N314	Euangi	New Actice LX @ 534.282
9 Jun 2010	N319	Banyabba	Removed
9 Jun 2010	N320	CamiraCreek	Removed
7 Jun 2010	N417	Milvale	New loop under construction
7 Jun 2010	N316	Nana Glen	New Active RLX @ 638.858
3 Jun 2010	N411	Yarrabandai	Yard Re-configured
2 Jun 2010	N308	Taree	Moved Signal 21-2
2 Jun 2010	N318	Grafton	Added RLX ID Numbers
2 Jun 2010	N319	Koolkhan	Added RLX ID Numbers
29 May 2010	N408	Menindee	New Active RLX @ 1006.910
26 May 2010	N417	Quandialla	New Loop Under Construction
21 May 2010	N305	South Craven	New Active RLX @ Woods Rd
18 May 2010	N252	Gerogery	Olympic Way Overpass added
18 May 2010	N253	Passing Loop 14	Developments added (not yet commissioned)
18 May 2010	N267	Jerrawa	New Active RLX ID 362
18 May 2010	N268	Oolong	New Active RLX ID 360
18 May 2010	N318	Grafton	New Active RLX @ Carrs Peninsula Rd
18 May 2010	N319	Koolkahn	New Active RLX @ Red Lane
18 May 2010	N415	Garema	Siding Removed
18 May 2010	N416	Wirrinya	New sign
18 May 2010	N417	Bribbaree	New Active RLX ID 112 and MLI
18 May 2010	N418	Stockinbingal	New Active RLXs ID 111 & 266
30 Apr 2010	N411	Derriwong	New active RLX @ 528.370 & Signal changes
30 Apr 2010	N417	Bribbaree	New active RLX @ 500.272 & Signal changes

30 Apr 2010	N418	Stockinbingal	New active RLX @ 452.764
30 Apr 2010	N269	Goulburn	Corrected km of Mundy St Bridge
21 Apr 2010	N413	Goobang Junction	New drawing link to Parkes CRN
21 Apr 2010	N415	Parkes Triangle	New drawing link to Parkes CRN
14 Apr 2010	N314	Nambucca Heads	Urunga moved to this sheet and new active RLX @ 576.075
14 Apr 2010	N315	Raleigh	Urunga moved to this sheet and new active RLX @ 582.820
14 Apr 2010	N323	Wiangaree	RLX ID now 499
10 Apr 2010	N268	Breadalbane	LX disyances corrected
10 Apr 2010	N272	Tallong	Signal MY6 re-labelled
9 Apr 2010	N313	Kempsey	New protected L/X @ 515.875
9 Apr 2010	N314	Eungai	New protected L/X @ 538.542
9 Apr 2010	N320	Leeville	Removal of Leeville signalling
9 Apr 2010	N321	Casino	Changes aspect of Sig 52-3
9 Apr 2010	N411	Yarrabandri	Corrected distance
9 Apr 2010	N459	Springridge	New protected L/X @ 557.336
6 Mar 2010	N312	Kundabung	Dn Distant moved in ppn for loop extension
19 Feb 2010	N459	Connemarra	New protected L/X @ 503.480
19 Feb 2010	N308	Killawarra	New protected L/X @ 362.886
19 Feb 2010	N305	Wards River	New protected L/X @ 285.084
12 Feb 2010	Q353	Greenbank	Turnouts converted to dual gauge
12 Feb 2010	Q351	Glenapp	Addedd mising engineers siding
21 Jan 2010	N267	Jerrawa	Active RLX commissioned at 296.823
21 Jan 2010	N268	Oolong	Active RLX commissioned at 249.035 & 288.173
12 Jan 2010	N409	Ivanhoe	New signalling protocol
21 Dec 2009	N279	Macarthur	New XO & TO for SSFL
18 Dec 2009	N323	Loadstone	New road bridge
17 Dec 2009	N459	Connemurra	2A points removed
14 Dec 2009	N271	Carrick	RLX numbered 341
11 Dec 2009	N271	Carrick	New active RLX @ 204.970
11 Dec 2009	N264	Wallendbeen	Minor typo
11 Dec 2009	N270	Goulburn	Corrected distances
11 Dec 2009	N269	Joppa Jcn	Corrected distances
11 Dec 2009	N268	Yarra	New active RLX @ 235.186

11 Dec 2009	N266	Galong	Replaced last semaphore signals with 3 aspect colour light
29 Nov 2009	N415	Forbes	New RLX protection @ Bathurst St (596.163)
16 Nov 2009	N291	Callawa	Iona Park Rd RLX is predictor
10 Nov 2009	N251	Albury	South end signal changes
5 Nov 2009	N323	Loadstone	Loop extension
4 Nov 2009	N273	Exeter	Yarrawa St Ped Xing ID No. Added
4 Nov 2009	N275	Bowral	Bowral St Ped Xing ID number added
4 Nov 2009	N291	Callawa	Iona Prak Rd RLX ID number
2 Nov 2009	N456	Troy Junction	Signs for Coonamble line now TO working
2 Nov 2009	N303	Kilbride	Loop extension rearrangements
29 Oct 2009	N310	Kerewong	Loop length now 1598m
29 Oct 2009	N302	Mindaribba	New loop on down
18 Oct 2009	N303	Kilbride	Loop extended to 1500m
18 Oct 2009	N415	Garema	Siding available for track machine storage
18 Oct 2009	N719	Botany Yard	New Xover 56A/B
12 Oct 2009	N291	Calwalla	Added protection @ Iona Park Rd RLX
12 Oct 2009	N306	Gloucester	Reinstate Frame E
12 Oct 2009	N409	Darnick	Remove Frame B
23 Sep 2009	N253	Culcairn	Added new Up PL14 TO
16 Sep 2009	N251	Albury	Changed Down end of Platform track arrangement
16 Sep 2009	N253	Culcairn	Added new Down PL14 TO
16 Sep 2009	N310	Kerewong	Additional loop length
16 Sep 2009	N311	Kerewong	Kerewong tunnel to drg310
30 Aug 2009	N265	Demondrille	Cowra Line closed
27 Aug 2009	N305	South Craven	Repositioned Woods Rd (St)
26 Aug 2009	N251	Albury	Removed broad gauge
26 Aug 2009	N273	Moss Vale	Added Ped Xing @ 146.893
26 Aug 2009	N275	Bowral	Added Ped Xing @ 136.995
12 Aug 2009	N411	Derriwong	Loop removed & assigned as Block Point
11 Aug 2009	N320	Camira Creek	Labelled as Block Point
5 Aug 2009	N308	Taree	RIC siding (Frame B) removed
5 Aug 2009	N302	Mindaribba	Loop extended to 1562m. Higher speed signalling commissioned
28 Jul 2009	N406	Broken Hill	Revised signal number displays (added 'BH')